Asarco El Paso Smelter - Cost Estimate Waste Ma		t Value Cal	culation]	
Sitewide Evaluation - El Paso, Texa				
·	Quantities	units	Unit Price	Total
Iomalitian of Structures [One time]				
Demolition of Structures [One time]  Demolition of Structures (steel)	264,141	sq. ft.	\$11	\$2,905,55
Demolition of Structures (Steer)  Demolition of Structures (Brick and concrete)	191,157		\$17.50	\$3,345,24
Demolition of Structures (Wood railroad trussels)	40,025		\$40	\$1,601,00
Demolition of Structures (I-10 Bridge and Slag bridge)	17,625		\$16	\$282,00
Demo	1	Lump Sum	\$750,000	\$750,00
Subtotal of demolition of structure				\$8,883,79
Froundwater [construction and 50 years operation]				
Construction [One time]				
Slurry Wall (Bentonite soil mix, 3 feet wide) Design and installation	3,000		\$590	\$1,770,00
Additional Extraction Wells will use existing wells whenever possible	50		\$4,500	\$225,00
Injection Well (800 foot injection well for discharge of treated groundwater)			\$100,000	\$100,00
Design and Construction of Groundwater Treatment system	1	system	\$5,000,000	\$5,000,00
Subtotal of Groundwater construction	27			\$7,095,00
Continuous operation [Present value of 50 years annuity factor of 25.72976		Annual Cost	£250,000	CO 00E 44
Operation and Maintenance (electrical and general maintenance)  Guard to protect equipment and GW system (1 guard \$ 25 an hour)		Annual Cost Annual Cost	\$350,000 \$213,600	\$9,005,41 \$5,495,87
Monitor Well Plugging and Abandonment [One time charge 50 years later, i		Annual Cost	\$213,000	\$5,495,67
Presnet Value factor of 0.22811 ]		Lump Sum	\$64,800	\$14,78
Semi-annual groundwater reports [2 reports per year @ \$5000 per report]		Annual Cost	\$10,000	\$257,29
Subtotal of Groundwater operation			, .,	\$14,773,37
Subtotal of Groundwater construction and operation	•			\$21,868,37
Asphalt Paving to manage exposure [One time]				
Acreage left to be paved from May 20, 2005 Corrective Action Directive letter	16	acres	\$130,000	\$2,080,00
Northern Section of Smelter	8		\$130,000	\$975,00
Former Building and Process footprint	52		\$130,000	\$6,760,00
Subtotal of apshalt paving	<u> </u>		<b>4</b> 100,000	\$9,815,00
Fen	2800	feet	\$25	\$68,62
<u>v.i.</u>	2000	1001	<del>+20</del>	<del>+++++++++++++++++++++++++++++++++++++</del>
ngineering Design and Construction of Disposal unit Cell 4 [One time]				
Engineer and Construction of Cell 4 for disposal of:	1	Cell	\$4,000,000	\$4,000,00
Minus 50 Slag waste pile (255,111 cubic yds)				
Abrasive Blasting Area (1,111 cubic yds.)				
Soil underneath Process area ( 20,000 cubic yds Estimated)				
Category I soils from May 5, 2005 letter (25,000 cubic yds Estimated)				
Excavation and Disposal of material in Cell 4 [One time]		cubic yds.	\$6	\$1,818,00
Verification of Waste Excavation of materials to Cell 4		soil samples	\$250	\$25,00
Completion Report  Subtotal of design and construction of disposal unit cell 4	1	report	\$5,000	\$5,00 <b>\$5,848,00</b>
oubtotal of acoign and construction of alopodal unit con-				ψ0,040,00
and these manifesting of anning spine control and appropriate (Decemb Value of		or of 33.333]		
		reports	\$0	\$
Annual site inspection report is covered under the groundwater report for the first	22 222	Annual Cost	\$9,000	\$299,99
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa	1: -7		\$11,024	\$367,46
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight	33.333	Annual Cost		
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year)	33.333 33.333	Annual Cost	\$1,000	
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year)  Anna	33.333 33.333			
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year) Anna General repairs per year (Fence and Asphalt Cap)	33.333 33.333 33.332	Annual Cost Annual Cost	\$1,000 \$5,000	\$166,66
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year) Anna General repairs per year (Fence and Asphalt Cap) Assume 1% of fence is required repair [1300 lf x \$25 LF]	33.333 33.333 33.332	Annual Cost Annual Cost Annual Cost	\$1,000 \$5,000 \$32,500	\$166,66 \$1,083,32
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year) Anna General repairs per year (Fence and Asphalt Cap) Assume 1% of fence is required repair [1300 lf x \$25 LF] Assume 0.5% of 98 Acres asphalt cover is required repair [\$2.00/sf x 20,0	33.333 33.333 33.332	Annual Cost Annual Cost	\$1,000 \$5,000	\$166,66 \$1,083,32 \$1,333,32
Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year) Anna General repairs per year (Fence and Asphalt Cap) Assume 1% of fence is required repair [1300 lf x \$25 LF] Assume 0.5% of 98 Acres asphalt cover is required repair [\$2.00/sf x 20,0 Subtotal of long term monitoring	33.333 33.333 33.332 33.333 00 SFJ 33.333	Annual Cost Annual Cost Annual Cost Annual Cost Annual Cost	\$1,000 \$5,000 \$32,500 \$40,000	\$33,33 \$166,66 \$1,083,32 \$1,333,32 \$3,284,09
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight  TCEQ travel (once a year)  Anna  General repairs per year (Fence and Asphalt Cap)  Assume 1% of fence is required repair [1300 if x \$25 LF]  Assume 0.5% of 98 Acres asphalt cover is required repair [\$2.00/sf x 20,0 Subtotal of long term monitoring	33.333 33.333 33.332 33.333 00 SFJ 33.333	Annual Cost Annual Cost Annual Cost	\$1,000 \$5,000 \$32,500	\$166,66 \$1,083,32 \$1,333,32 \$3,284,09 \$
Annual site inspection report is covered under the groundwater report for the first Monitoring and Sampling (Management of Waste) 30 wells biannual (\$150 per sa TCEQ Oversight TCEQ travel (once a year) Anna General repairs per year (Fence and Asphalt Cap) Assume 1% of fence is required repair [1300 lf x \$25 LF] Assume 0.5% of 98 Acres asphalt cover is required repair [\$2.00/sf x 20,0	33.333 33.333 33.332 33.333 00 SFJ 33.333	Annual Cost Annual Cost Annual Cost Annual Cost Annual Cost	\$1,000 \$5,000 \$32,500 \$40,000	\$166,66 \$1,083,32 \$1,333,32

1 of 2 2/10/2009 9:43 AM

http://newspapertree.com/system/news\_article/document1/3432/ASAR...

2 of 2